
CITY OF THE CHEQUERED PAST

PORTFOLIO


LOCATION IN CZECH REPUBLIC



LOCATION IN PRAGUE



WIDER REALTIONS



TIMELINE - SOUTH CITY


```
1185 first mention
1618–1648 Thirty Year's War – Jiří Vllém Michna z Vacínova
1676 Benedictine monastery of St. Nicolas
1728 sold to owner of Kunratice
1848 Chodov, Litochleby, Šeberov and Hrnčíře formed one village
1908 Šeberov and Hrnčíře were separated
1918 Chodov excluded from the Great Prague plans
1920s Chodov sold to Prague, became separated village as well
as Háje which separated from Hostivař
1949 part of "Praha - východ"
1959 JZD Chodov
1960 part of "Praha - západ"
1960s D1 and water piping frome Želivka river are being built
using the area of Prague 11
1968 Praha 4
1990 Praha 11
1994 name "Praha - Jižní Město"
```

PHOTODOCUMENTATION FROM THE SITE - HÁJE




























ANALYSIS: SUNLIGHT



20. 3. & 22. 9. 8:55 beginning of 50% litted space



20. 3. & 22. 9. 16:58 end of 50% litted space




21. 6. 8:25 beginning of 50% litted space



21. 6. 18:58 end of 50% litted space




21. 12. 10:26 beginning of 50% litted space




21. 12. 14:12 end of 50% litted space

ANALYSIS: TOPOGRAPHY



ANALYSIS: OWNERSHIP



ANALYSIS: ENGINEERING NETWORKS



SWOT ANALYSIS

S - STRENGHTS

living space
quantity of shops and services
mature vegetation
close to the metro station
pleasant microclimate under the trees
good transport accessibility

0 - OPPORTUNITIES

increasing attractiveness for locals
operating functional road network
rainwater treatment, permeable surfaces
unity of materials
utilization of non-functional space

W - WEAKNESSES

unused spaces

diversity of materials

visual smog (advertising stickers and sheets)

bad permeability through the territories (connection of paths)

bad connection and zone breakdown

bad health of vegetation

impermeable surfaces

insufficient maintenance

T - THREATS

harassment by drunk people, homeless people


injuries at the interface of various surfaces

threats of falling trees


vandalism

the threat of clutter

HISTORICAL ORTOPHOTO











CONCEPT KEYWORDS

CHEQUERED HISTORY
CHEQUERED AREA
CHEQUERED ZONING




ZONING



- 1_PUBLIC PLAZA
- 2_PUBLIC BOSKET
- 3_WAVY LANDSCAPE
- **4_NEIGHBOUR BOSKET**
- 5_REFRESHMENT ZONE

2	3	4
1		5













SECTION VIEW A-A' scale 1:250



SECTION VIEW B-B' scale 1:250



VEGETATION



TREES





1)Tilia cordata

2) Betula pendula

VINE

SHRUBS







3) Syringa vulgaris

4) Lonicera periclymenum 5) Aristolochia macro-

PERENNIALS








6) Red low prairie

7) Crocus flavus & Cornus chrysanthus

7) Corcus napolitanus

RAINWATER MANAGEMENT SCHEME



PUBLIC LIGHTING

